



Seasonal Posting Exceptions

May. 16, 2012

| Zone | District | Route | Begin | End | Description | Axle Limit | Start | End | Comments |
|-------------|-----------------|--------------|--------------|------------|-------------------------|-------------------|---------------|----------------------|---|
| C | 4 | 7 | 0 | 24.182 | Golf Club Road to TH 28 | 7 tons | Apr. 29, 2011 | Until further notice | Requires reconstruction to increase load rating |
| S | 8 | 277 | 2.5 | 11.02 | Glueck to TH 40 | 5 tons | Mar. 06, 2012 | Until further notice | Weak base requires load limit to prevent breakups |